



Vehicle History Report™

US \$39.99

2021 VOLKSWAGEN ATLAS SE

VIN: 1V2HR2CA1MC540534
4 DOOR WAGON/SPORT UTILITY
3.6L V6 F DOHC 24V
GASOLINE
ALL WHEEL DRIVE



Damage reported: airbag deployed



CARFAX 1-Owner vehicle



At least 1 open recall



Rental vehicle



7 Detailed records available



6,222 Last reported odometer reading

CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/8/22 at 10:33:47 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Ownership History

The number of owners is estimated

Owner 1

Year purchased	2020
Type of owner	Rental
Estimated length of ownership	3 months
Owned in the following states/provinces	Maryland
Estimated miles driven per year	---
Last reported odometer reading	6,222



Title History

CARFAX guarantees the information in this section



Owner 1

Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem



GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. [View Terms](#) | [View Certificate](#)




Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment Airbag deployment reported: 03/17/2021.	Airbag Deployment
Odometer Check	<input checked="" type="checkbox"/> No Issues Indicated

No indication of an odometer rollback.	
Accident / Damage Damage reported: 03/17/2021.	Damage Reported
Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized Volkswagen dealer to obtain more information about this recall.	Recall Reported
Basic Warranty Original warranty estimated to have 34 months or 43,778 miles remaining.	 Warranty Active






Detailed History

Owner 1

Purchased: 2020

Rental Vehicle

Date	Mileage	Source	Comments
12/04/2020		NICB	Vehicle manufactured and shipped to original dealer
12/17/2020	11	Maryland Motor Vehicle Dept. Linthicum Heights, MD Title #53674491	Title or registration issued - First owner reported - Titled or registered as rental vehicle
03/17/2021		Damage Report	 <p>Damage reported: minor to moderate damage</p> <ul style="list-style-type: none"> - Damage to rear - Airbag deployed <p>CARFAX Airbag Tips</p> <p>This incident was first available for display by CARFAX on 04/08/2021.</p> <div data-bbox="852 1055 1414 1252" data-label="Figure"> <p>Damage Severity Scale ⓘ</p>  <p>MINOR MODERATE SEVERE</p> </div> <div data-bbox="852 1285 1414 1868" data-label="Diagram"> <p>Damage Location</p>  <p>FRONT</p> <p>LEFT RIGHT</p> <p>REAR</p> </div>
03/22/2021	6,222	Auto Auction	Vehicle sold
03/25/2021		Fleet/Lease Company	Vehicle sold
05/29/2021		Vehicle Exporter	Vehicle exported from - Savannah, GA and imported to - The Netherlands
11/24/2021		Volkswagen	Manufacturer Safety Recall issued

CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION



- NHTSA #21V892
- Recall #87H4 AIR CONDITIONING WATER DRAIN TUBE
- Status: Remedy Available
- Locate an authorized [Volkswagen dealer](#) to obtain more information about this recall
- [Learn more about this recall](#)

Description: The water drain tube of the air conditioning system could become blocked. If this happens, water can accumulate and leak inside the vehicle, and may contact the airbag control module. This can cause airbag system malfunctions, including unwarranted airbag deployment. This may increase the risk for an injury or may lead to a crash without warning. If this condition is present in the vehicle, the airbag warning light may illuminate if a malfunction is detected.

Remedy: Affected vehicles will be inspected and, if a blocked drain tube is found, repaired. The airbag control unit will be replaced for those vehicles where a blocked drain tube was found.

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

Airbag Deployment

Occurs when the driver, passenger or side airbag has been used or deployed during a crash or other incident. If an airbag has been deployed, it must be replaced by a qualified technician. Have this car inspected by a mechanic prior to purchase.

Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/8/22 at 10:33:47 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform owners of car defects that have come to the manufacturer's attention. Recalls also suggest improvements that can be made to improve the safety of a particular vehicle. Most manufacturer recalls can be repaired at no cost to you.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Rental

Vehicle was registered by a rental agency.

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2022 CARFAX, Inc., a unit of IHS Markit Ltd. All rights reserved.
3/8/22 10:33:47 AM (CST)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2021 VOLKSWAGEN ATLAS vehicle (VIN: 1V2HR2CA1MC540534), which is based on information supplied to CARFAX and available as of 3/8/22 at 11:33 AM (EST).

Customer Signature

Date

Dealer Signature

Date